IECEx Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION
IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **GB/SIR/QAR06.0055/12**

QAR Free Ref. No.: **80305034**

Status:**Issued**

Details of change: Recertification Audit

Date of issue:**2026-10-23**

Location(s) audited: **Victor Products Limited**
Unit 3A, Tyne Dock East Side
Port of Tyne
South Shields, Tyne & Wear NE33 5SQ
United Kingdom

Valid until:**2029-11-17**

Audit date:**2026-10-13**

Issuing ExCB: **CSAE - CSA Group Testing UK Ltd**

Manufacturer: **Victor Products Limited**
Unit 3A, Tyne Dock East Side
Port of Tyne
South Shields, Tyne & Wear NE33 5SQ

Location of Manufacturer: **United Kingdom**

Product information: Luminaires, in-line bushings, terminal boxes, enclosures, cable attachments.

Type of protection: **Ex d.**

Related QARs:

GB/SIR/QAR06.0055/00
GB/SIR/QAR06.0055/01
GB/SIR/QAR06.0055/02
GB/SIR/QAR06.0055/03
GB/SIR/QAR06.0055/04
GB/SIR/QAR06.0055/05
GB/SIR/QAR06.0055/06
GB/SIR/QAR06.0055/07
GB/SIR/QAR06.0055/08
GB/SIR/QAR06.0055/09
GB/SIR/QAR06.0055/10
GB/SIR/QAR06.0055/11

Related Certificates (manual insertion)::

IECEx SIR 05.0008U

Related Certificates (automatic linking)::

Related Certificates for previous versions:

IECEx BAS 09.0048U issue: 0
IECEx BAS 09.0048U issue: 1
IECEx BAS 09.0048U issue: 2
IECEx BAS 09.0048U issue: 3
IECEx BAS 09.0048U issue: 4
IECEx BAS 09.0048U issue: 5
IECEx BAS 09.0048U issue: 6
IECEx BAS 09.0048U issue: 7
IECEx BAS 09.0048U issue: 8
IECEx BAS 09.0049X issue: 0
IECEx BAS 09.0049X issue: 1
IECEx BAS 09.0049X issue: 2
IECEx BAS 09.0049X issue: 3
IECEx BAS 09.0049X issue: 4
IECEx BAS 09.0049X issue: 5
IECEx BAS 13.0122U issue: 0
IECEx BAS 13.0122U issue: 1
IECEx BAS 14.0185X issue: 0
IECEx BAS 14.0185X issue: 1
IECEx ITS 08.0012 issue: 0
IECEx ITS 08.0012 issue: 1
IECEx ITS 08.0012 issue: 2
IECEx SIR 06.0055X issue: 0
IECEx SIR 06.0055X issue: 1
IECEx SIR 06.0091X issue: 1
IECEx SIR 06.0091X issue: 2
IECEx SIR 06.0091X issue: 3
IECEx SIR 09.0134 issue: 0
IECEx SIR 09.0134 issue: 1
IECEx SIR 09.0134 issue: 2
IECEx SIR 09.0134 issue: 3
IECEx SIR 10.0173U issue: 0
IECEx SIR 10.0173U issue: 1
IECEx SIR 10.0173U issue: 2
IECEx SIR 10.0173U issue: 3
IECEx SIR 13.0152 issue: 0
IECEx SIR 13.0152 issue: 1

Comments: