



# IECEX Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.:	<b>GB/SIR/QAR06.0055/08</b>	Page 1 of 1
QAR Free Ref. No.:	<b>80055670/1</b>	Status: <b>Issued</b>
Details of change:	Recertification Audit	Date of issue: <b>2020-11-09</b>
Site(s) audited:	<b>Victor Products Ltd,</b> Unit 3A, Tyne Dock East Side Port of Tyne South Shields NE33 5SQ United Kingdom <b>United Kingdom</b>	Valid until: <b>2023-11-17</b>  Audit date: <b>2020-10-28</b>
Issuing ExCB:	<b>SIR - SIRA Certification Service</b>	
Manufacturer:	<b>Victor Products Ltd,</b> Unit 3A, Tyne Dock East Side Port of Tyne South Shields NE33 5SQ United Kingdom	
Location of Manufacturer:	<b>United Kingdom</b>	
Product information:	luminaires, in-line bushings, terminal boxes, enclosures, cable attachments	
Protection concept:	<b>Ex d, m</b>	
Related QARs:		
<a href="#">GB/SIR/QAR06.0055/00</a>	<a href="#">GB/SIR/QAR06.0055/01</a>	<a href="#">GB/SIR/QAR06.0055/02</a>
<a href="#">GB/SIR/QAR06.0055/03</a>	<a href="#">GB/SIR/QAR06.0055/04</a>	<a href="#">GB/SIR/QAR06.0055/05</a>
<a href="#">GB/SIR/QAR06.0055/06</a>	<a href="#">GB/SIR/QAR06.0055/07</a>	
Related Certificates (manual insertion)::		
<b>IECEX SIR 05.0008U</b>		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:		
<a href="#">IECEX BAS 09.0048U issue: 0</a>	<a href="#">IECEX BAS 09.0048U issue: 1</a>	<a href="#">IECEX BAS 09.0048U issue: 2</a>
<a href="#">IECEX BAS 09.0048U issue: 3</a>	<a href="#">IECEX BAS 09.0048U issue: 4</a>	<a href="#">IECEX BAS 09.0048U issue: 5</a>
<a href="#">IECEX BAS 09.0048U issue: 6</a>	<a href="#">IECEX BAS 09.0048U issue: 7</a>	<a href="#">IECEX BAS 09.0049X issue: 0</a>
<a href="#">IECEX BAS 09.0049X issue: 1</a>	<a href="#">IECEX BAS 09.0049X issue: 2</a>	<a href="#">IECEX BAS 09.0049X issue: 3</a>
<a href="#">IECEX BAS 09.0049X issue: 4</a>	<a href="#">IECEX BAS 13.0122U issue: 0</a>	<a href="#">IECEX BAS 13.0122U issue: 1</a>
<a href="#">IECEX BAS 14.0185X issue: 0</a>	<a href="#">IECEX BAS 14.0185X issue: 1</a>	<a href="#">IECEX ITS 08.0012 issue: 0</a>
<a href="#">IECEX SIR 06.0055X issue: 0</a>	<a href="#">IECEX SIR 06.0055X issue: 1</a>	<a href="#">IECEX SIR 06.0091X issue: 1</a>
<a href="#">IECEX SIR 06.0091X issue: 2</a>	<a href="#">IECEX SIR 06.0091X issue: 3</a>	<a href="#">IECEX SIR 09.0134 issue: 0</a>
<a href="#">IECEX SIR 09.0134 issue: 1</a>	<a href="#">IECEX SIR 09.0134 issue: 2</a>	<a href="#">IECEX SIR 10.0173U issue: 0</a>
<a href="#">IECEX SIR 10.0173U issue: 1</a>	<a href="#">IECEX SIR 10.0173U issue: 2</a>	<a href="#">IECEX SIR 13.0152 issue: 0</a>
<a href="#">IECEX SIR 13.0152 issue: 1</a>		
Comments:		