

IECEx Quality Assessment Report Summary

Audit date: 2023-09-12

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **GB/SIR/QAR06.0055/10** Page 1 of 1

QAR Free Ref. No.: 80179668/80179669/80179670 Status:Issued

Details of change: 2023 Recertification Audit Date of issue: 2023-11-08

Location(s) audited: Victor Products Ltd, Valid until:2026-11-17

Unit 3A, Tyne Dock East Side Port of Tyne

South Shields NE33 5SQ United Kingdom United Kingdom

Issuing ExCB: CSAE - CSA Group Testing UK Ltd

Manufacturer: Victor Products Ltd,

Unit 3A, Tyne Dock East Side

Port of Tyne South Shields NE33 5SQ United Kingdom

Location of Manufacturer:

United Kingdom

Product information: luminaires, in-line bushings, terminal boxes, enclosures, cable attachments

Type of protection: Ex d,

Related QARs:

GB/SIR/QAR06.0055/00 GB/SIR/QAR06.0055/01 GB/SIR/QAR06.0055/02 GB/SIR/QAR06.0055/03 GB/SIR/QAR06.0055/04 GB/SIR/QAR06.0055/05 GB/SIR/QAR06.0055/06 GB/SIR/QAR06.0055/07 GB/SIR/QAR06.0055/08 GB/SIR/QAR06.0055/09

Related Certificates (manual insertion)::

IECEx SIR 05.0008U

Related Certificates (automatic linking)::

Related Certificates for previous versions:

IECEx BAS 09.0048U issue: 0 IECEx BAS 09.0048U issue: 1 IECEx BAS 09.0048U issue: 2 IECEx BAS 09.0048U issue: 3 IECEx BAS 09.0048U issue: 4 IECEx BAS 09.0048U issue: 5 IECEx BAS 09.0048U issue: 6 IECEx BAS 09.0048U issue: 7 IECEx BAS 09.0048U issue: 8 IECEx BAS 09.0049X issue: 0 IECEx BAS 09.0049X issue: 1 IECEx BAS 09.0049X issue: 2 IECEx BAS 09.0049X issue: 3 IECEx BAS 09.0049X issue: 4 IECEx BAS 09.0049X issue: 5 IECEx BAS 13.0122U issue: 0 IECEx BAS 13.0122U issue: 1 IECEx BAS 14.0185X issue: 0 IECEx BAS 14.0185X issue: 1 IECEx ITS 08.0012 issue: 0 IECEx ITS 08.0012 issue: 1 IECEx ITS 08.0012 issue: 2 IECEx SIR 06.0055X issue: 0 IECEx SIR 06.0055X issue: 1 IECEx SIR 06.0091X issue: 1 IECEx SIR 06.0091X issue: 2 IECEx SIR 06.0091X issue: 3 IECEx SIR 09.0134 issue: 0 IECEx SIR 09.0134 issue: 1 IECEx SIR 09.0134 issue: 2 IECEx SIR 09.0134 issue: 3 IECEx SIR 10.0173U issue: 0 IECEx SIR 10.0173U issue: 1 IECEx SIR 10.0173U issue: 2 IECEx SIR 10.0173U issue: 3 IECEx SIR 13.0152 issue: 0 IECEx SIR 13.0152 issue: 1

Comments: